

**A STUDY ON MEETING THE 3.0% ALLOWABLE REJECT RATE ON
PRODUCING SEAT MOLE AT TOPTECH PARTS MANUFACTURING INC.**

A Practicum Study Presented to

The Faculty of Industrial Engineering Department
College of Engineering, Architecture and Technology

De La Salle University- Dasmariñas
Dasmariñas, Cavite

In Partial Fulfillment of the requirements for the Degree of
Bachelor of Science in Industrial Engineering

Submitted By:

ENRIQUEZ, KIMBERLY S.

IEE52

Submitted To:

Engr. Ma. Estrella Natalie B. Pineda

MARCH 2014

ABSTRACT

This study is about Quality Control. The research was conducted at Toptech Parts Manufacturing Inc., located at Brgy. Real Calamba City, Laguna. The observation was done in the production of Seat Mole at stamping section. Through interview and gathering of data from the staff in the production, the problem is identified. The company has experienced 12.68% rejects amounting to Php 1,219,629.70 from the month of July to December 2013. Hence, the company exceeding 9.68 % allowable reject rate. In this study, the root causes of the problems were also determined and proposed alternative courses of action to prevent the occurrence of rejects. The objectives will be achieved if the alternative courses are being implemented.



TABLE OF CONTENTS

Title Page

Approval Sheet

Acknowledgement

Abstract

Table of Contents

List of Tables and Figures

CHAPTER I: INTRODUCTION.....	1
Company Profile.....	1
Background of the Study.....	2
Problem Statement	3
Objectives of the Study.....	3
Scope and Limitation of the Study.....	4
Significance of the Study.....	4
Methodology.....	5
Definition of Terms.....	8
CHAPTER II: REVIEW OF RELATED LITERATURE.....	9
CHAPTER III: PRESENTATION AND ANALYSIS OF DATA.....	22
3.1 Presentation and analysis of data.....	22
3.2 Product description.....	23
3.3 Process Flow chart.....	24
	6


3.4 Fishbone Diagram.....	25
3.5 Die.....	27
3.6 Unbalance forming.....	28
3.7 Deformed.....	28
3.8 Not good knotching.....	29
3.9 Deformed raw materials.....	30
3.10 Scratches.....	33
3.11 Checksheet.....	34
3.12 Pareto Chart.....	44
3.13 Why Why Analysis.....	37
CHAPTER IV: ANALYSIS OF GATHERED DATA.....	38
Problem Tree.....	38
Problem Tree Analysis.....	39
Objective Tree.....	41
Objective Tree Analysis.....	42
CHAPTER V: ALTERNATIVE COURSES OF ACTION.....	44
ACA 1: Provide New Die.....	44
ACA 2: Provide sanctions to negligent workers	48
ACA 3: Provide a properly designed storage rack o	
raw materials	54
Cost Benefit Analysis.....	57

CHAPTER VI: CONCLUSION AND RECOMMENDATIONS.....	58
Conclusion.....	58
Recommendations.....	58
CHAPTER VII: DETAILED PLAN OF ACTION.....	59
Gantt Chart.....	59
Detailed Plan of Action.....	60
BIBLIOGRAPHY.....	62

APPENDICES

CURRICULUM VITAE

PICTURE



LIST OF TABLES AND FIGURES

Tables

Table 3.1 Reject Rate from the month June 2013 to November 2013.....	21
Table 3.2 Fishbone computation breakdown	25
Table 3.3 Summary of rejects of due to worn out die	28
Table 3.4 Summary of rejects due to no proper storage of raw materials.....	29
Table 3.5 Summary of rejects due to of improper handling of raw materials.....	31
Table 3.6 Check sheet.....	32
Table 3.7 Pareto chart.....	32
Table 3.8 Summary of rejects of seat mole.....	34
Table 3.9 Why Why Analysis.....	35

Figures

Figure 3.1 Process Flow of Seat mole.....	23
Figure 3.2 Fishbone diagram	24
Figure 3.3 Handling procedure.....	32
Figure 3.4 Pareto diagram.....	35
Figure 3.5 Fishbone Diagram.....	40
Figure 4.1 Problem Tree.....	63
Figure 4.2 Objective Tree.....	67

Figure 5.1 Knotching Die.....	44
Figure 5.2 Forming (upper)	44
Figure 5.3 Forming (lower)	44
Figure 5.4 Existing Procedure of handling materials in the storage area.....	48
Figure 5.5 Proposed Disciplinary Action for Mishandled materials....	49
Figure 5.6 Side view of proposed rack.....	54
Figure 5.7 Top view of proposed rack.....	54

Pictures

Picture 3.1 Seat mole.....	22
Picture 3.2 Forming 1- lower.....	26
Picture 3.3 Forming 3.3.....	26
Picture 3.4 Knotching die	26
Picture 3.5 Unbalanced Forming.....	27
Picture 3.6 Unbalanced Forming	27
Picture 3.7 Unbalanced Forming	27
Picture 3.8 Deformed.....	27
Picture 3.9 Not good Knotching.....	28
Picture 3.10 Deformed raw materials	29
Picture 3.11 Deformed raw materials	29
Picture 3.12 racks and Bin.....	30
Picture 3.13 Scratches.....	32
Picture 5.1 Racks and bin.....	53