

**A Study on Eliminating the the 17.94% Productivity Loss in Producing  
Lady's Choice Mayonnaise 3.5 L in Unilever Philippines Inc.**

A Practicum Study Presented to the Faculty of the  
College of Engineering Architecture and Technology  
De La Salle University – Dasmariñas

Dasmariñas, Cavite

In Partial Fulfillment  
of the Requirements for the Degree of  
Bachelor of Science in Industrial Engineering

**Submitted By:**

BASE, Arielle A.

IEE52

**Submitted To:**

Engr. Ma. Estrella Natalie B. Pineda

**March 2014**

## ABSTRACT

This study is related in the field of Time and Motion Study. The research was conducted at Unilever Philippines located at Gateway Business Park General Trias, Cavite. The observation was done in the production of 3.5 L Lady's Choice Mayonnaise where the researcher was assigned for her Practicum. Through interview and gathering of data from some of the staff in the production, where the problem is identified. The company has experienced a 17.94% of production loss from the month of July to December 2013. The root causes of the problems were also determined in this study. After determining the root causes of the problems, the researcher proposed alternative courses of action to prevent the occurrence of such problems. When alternative courses of action are implemented objectives of the study will be achieved.

## Table of Contents

<b>Title Page</b> .....	i
<b>Approval Sheet</b> .....	ii
<b>Acknowledgements</b> .....	iii
<b>Abstract</b> .....	v
<b>Table of Contents</b> .....	vi
<b>List of Tables and Figures</b> .....	ix
<b>CHAPTER 1: INTRODUCTION</b> .....	1
Company Profile.....	2
Background of the Study .....	3
Problem Statement.....	4
Objectives of the Study.....	4
Scope and Limitation of the Study.....	5
Significance of the Study .....	6
Methodology.....	7
Definition of Terms .....	8
<b>CHAPTER 2: REVIEW OF RELATED LITERATURE</b> .....	9
History of Mayonnaise.....	9
Background Information of Mayonnaise .....	10

Materials and Methods .....	11
Nutrition .....	12
Food Safety and Quality .....	14
Manufacturing Mayonnaise.....	16
<b>CHAPTER 3: PRESENTATION OF GATHERED DATA .....</b>	<b>18</b>
Summary of Data from the Month of July to December 2013.....	18
Summary of Profit Loss Computation.....	19
Total Working Hours from July to December 2013.....	20
Process Flow Chart .....	21
Summary of Causes .....	22
Record of Seal Applicator Downtime.....	23
Actual Picture of Seal Applicator .....	24
Relabeling Process Time.....	25
Readjusting of Cover Caps.....	26
Fishbone Diagram .....	27
<b>CHAPTER 4: ANALYSIS OF GATHERED DATA .....</b>	<b>28</b>
Problem Tree.....	28
Problem Tree Analysis .....	29
Objective Tree .....	31
Objective Tree Analysis.....	32

<b>CHAPTER 5: ALTERNATIVE COURSES OF ACTION</b> .....	34
ACA 1: Find Appropriate Supplier.....	34
Existing Contract .....	36
Proposed Contract.....	38
ACA 2: Procurement of High Standard Paper used in Labeling Machine .....	41
ACA 3: Procurement of New Cart.....	45
Cost-Benefit Analysis .....	49
<b>CHAPTER 6: CONCLUSION AND RECOMMENDATIONS</b> .....	50
<b>CHAPTER 7: DETAILED PLAN OF ACTION</b> .....	51
Gantt Chart.....	51
Detailed Plan of Action .....	51
<b>BIBLIOGRAPHY</b> .....	52

## LIST OF TABLES

Table 3.1 Summary of Data from the month of July to December 2013 .....	18
Table 3.2 Total Working Hours from the month of July to December 2013 .....	20
Table 3.3 Summary of Causes .....	22
Table 3.4 Record of Seal Applicator Downtime .....	23
Table 3.5 Causes of Machine Breakdown of Seal Applicator .....	24
Table 3.6 Actual Time Study of Capping and Labeling Process .....	26
Table 3.7 Relabeling Processing Time .....	27
Table 3.8 Readjusting of Cover Caps .....	28
Table 5.1 Specification of Required Film and the Existing Film .....	38
Table 5.2 Existing and Proposed Paper Label .....	47
Table 5.3 Paper for Labelling Supplier –SWOT Analysis .....	50
Table 5.4 Existing and Proposed Cart for Refiling Cover Caps .....	55
Table 5.5 Cart Supplier –SWOT Analysis .....	58

## LIST OF FIGURES

Figure 3.1 Summary of Profit Loss Computation .....	19
Figure 3.2 Process Flow Chart .....	21
Figure 3.3 Actual picture of Seal Applicator.....	25
Figure 5.1 Crumpled Film in Mandrel Part of Seal Applicator.....	38
Figure 5.2 Other Products of Unilever with Aligned Labels .....	48
Figure 5.3 Lady's Choice Mayo with Misaligned Labels .....	49
Figure 5.4 Actual Labeling Machine of Line A .....	52
Figure 5.5 Dimensions of Existing Cart Used in Refiling Cover Caps.....	56
Figure 5.6 Proposed Cart Used in Refiling Cover Caps .....	57

