A STUDY ON MEETING THE 4.3% ALLOWABLE REJECT RATE IN THE PRODUCTION OF WIRING HARNESS OF YUMEX PHILIPPINES CORPORATION

A Practicum Study presented to the Faculty of
The College of Engineering, Architecture, and Technology
De La Salle University – Dasmariñas
Dasmariñas City, Cavite

In Partial Fulfillment
Of the Requirements for the Degree of
Bachelor of Science in Industrial Engineering

Submitted by:

ANABE, LEXTER A. IEE52

Submitted to:

Engr. Maria Estrella Natalie B. Pineda

February 2014

ABSTRACT

This study is related in the field of Quality Control. The research is conducted at Yumex Philippines Corporation located at First Cavite Industrial Estate, Bo. Langkaan, Dasmariñas City, Cavite. The observation was done in the production of Wiring Harness where the researcher was assigned for his practicum. Through interview and gathering of data from some of the staffs in the production, the problem is identified. The company has experienced 5.76% reject rate in the production in its production from the month of June 2013 to November 2013 amounting to PHP 1,025, 610. Thus, exceeding the 4.3% allowable reject rate of the company. The root causes of the problems were also determined in this study. After determining the root causes of the problems, the researcher proposed alternative courses of action to prevent the occurrence of such problems. When alternative courses of action are implemented objectives of the study will be achieved.

TABLE OF CONTENTS

Title Page	i
Approval Sheet	ii
Acknowledgement	iii
Abstract	v
Table of Contents	vi
List of Tables, Figures, and Pictures	
CHAPTER 1: INTRODUCTION	1
Company Profile	1
Background of the Study	
Problem Statement	4
Objectives of the Study	4
Scope and Limitation of the Study	5
Significance of the Study	5
Methodology	6
Definition of Terms	8
CHAPTER 2: REVIEW OF RELATED LITERATURE	11
History of Wires	11
Wiring Harness Production	13
Wire Cutting	14
Wire Crimping	14

	Application of Wiring Harness	16
	Defects in Wiring Harness	.16
	Repairs on Wiring Harnesses Defects	17
	Defect: Terminal Push Out (TPO)	.17
	Defect: Cross Circuit	18
	Inspection	18
	Process Inspection	19
	Final Inspection	20
	Manufacturing Cost Modelling for Electrical Interconnections	.20
	Develop Standard Operating Procedures in	
	Warehousing and Manufacturing	21
	Preventive Maintenance in a Multiple Shift	
	and High Volume Manufacturing Operation	.22
	OSHA'S final rule on operator training and how to comply	.23
	Five Proven Methods to Boost Operator Competency	
	with Simulator Training	24
	Operator training keeps small errors from piling up	25
CHAP	PTER 3: PRESENTATION OF GATHERED DATA	26
	Table 3.1 Reject Rate from the month	
	June 2013 to November 2013	26
	Figure 3.1 Process Flow of Wiring Harness Production	28
	Figure 3.2 Existing Wire Insertion Procedure	29
	Table 3.2 Summary of Defects from	

June 2013 to November 2013	30
Figure 3.3 Graphical Presentation of Defects	32
Figure 3.4 Problem Identification using Control Chart	35
Table 3.3 Why-Why Analysis of Failure Modes	38
Table 3.4 Top Defects and Cause of Occurrence	39
Figure 3.5 Fishbone Diagram	40
Figure 3.6 Mistake-Proofing (Poka-Yoke)	41
Table 3.5 Failure Mode and Effect Analysis (FMEA)	42
Picture 3.1 Actual Crimping Inspection	43
Picture 3.2 Actual Conduction Inspection	44
Picture 3.3 Actual FQA Inspection	45
Picture 3.4 Finished Goods: Wiring Harness (Company Product)	46
Picture 3.5 Parts of Wiring Harness	47
Picture 3.6 Evidence Sample of Deformed Terminal	48
Picture 3.7 Criteria for Good Crimping Condition of Terminal	49
Picture 3.8 Other Effects of No Proper Monitoring	
of Crimping Machines	50
Picture 3.9 Crimping Machine and its Components	53
Picture 3.10 Crimping Machine Sample Corrective Maintenance	55
Picture 3.11 Evidence of Corrective Maintenance	56
Picture 3.12 Evidence Sample of Wrong Location of Wire	57
Picture 3.13 Actual Wire Insertion Process in the Production	58
Picture 3.14 Sample of Common Process	

	OSG (Operation Standard Guide)	59
	Picture 3.15 Evidence Sample of Half-Inserted	. 61
	Picture 3.16 Other Effects due to No Standard	
	Procedure of Wire Insertion	. 62
CHAF	PTER 4: ANALYSIS OF GATHERED DATA	. 63
	Figure 4.1 Problem Tree	63
	Problem Tree Analysis	. 64
	Figure 4.2 Objective Tree	67
	Objective Tree Analysis	. 68
CHAF	PTER 5: ALTERNATIVE COU <mark>RS</mark> ES OF ACTION	70
	ACA 1: Provide Wire Connection Jig and Box Segregator	70
	Figure 5.1 Proposed Box Segregator of Wire Colors	. 71
	Figure 5.2 Proposed Wire Connection Jig	. 72
	Figure 5.3 Workstation Implementation Set-up for ACA 1	. 73
	Figure 5.4 New Procedure in the Workstation of	
	Wire Insertion Process	.74
	Figure 5.5 Workstation Standard Guide of Wire Insertion Process	75
	Figure 5.6 Plan-Do-Check-Act Cycle for ACA 1	. 76
	ACA 2: Provide Standard Procedure of Wire Insertion	. 77
	Figure 5.7 Proposed Standard Procedure of Wire Insertion	. 78
	Figure 5.8 Additional Checkpoint in Common Process	
	OSG (Operation Standard Guide)	.79
	Figure 5.9 Comparison of Existing Wire Insertion Procedure	

Recommendations	103
CHAPTER 7: DETAILED PLAN OF ACTION	104
Table 7.1 Gantt Chart	104
Detailed Plan of Action	106
BIBLIOGRAPHY	109
APPENDICES	112
Appendix A: Practicum Waiver	113
Appendix B: Recommendation Letter	114
Appendix C: Memorandum of Understanding	
Appendix D: Company Profile	118
Appendix E: On-The-Job Trainee Photos at	
Yumex Philippines Corporation	120
Appendix F: Validity of Presented Gathered Data	122
Appendix G: Validated On-The-Job Trainee Attendance Record	
Appendix H: Certificate of Employment	
Appendix I: Certificate of Proofread	125
Appendix J: Proofreader's License and Diploma	126
Appendix K: Researcher's Profile	128

LIST OF TABLES, FIGURES AND PICTURES

Tables

	Table 3.1 Reject Rate from the month	
	June 2013 to November 20132	26
	Table 3.2 Summary of Defects from	
	June 2013 to November 2013	30
	Table 3.3 Why-Why Analysis of Failure Modes	38
	Table 3.4 Top Defects and Cause of Occurrence	39
	Table 3.5 Failure Mode and Effect Analysis (FMEA)	12
	Table 5.1 Cost-Benefit Analysis	99
	Table 7.1 Gantt Chart	104
Figure	es s	
	Figure 3.1 Process Flow of Wiring Harness Production	28
	Figure 3.2 Existing Wire Insertion Procedure	29
	Figure 3.3 Graphical Presentation of Defects	32
	Figure 3.4 Problem Identification using Control Chart	35
	Figure 3.5 Fishbone Diagram	40
	Figure 3.6 Mistake-Proofing (Poka-Yoke)	11
	Figure 4.1 Problem Tree	63
	Figure 4.2 Objective Tree	67
	Figure 5.1 Proposed Box Segregator of Wire Colors	71

Figure	5.2 Proposed Wire Connection Jig	72
Figure	5.3 Workstation Implementation Set-up for ACA 1	73
Figure	5.4 New Procedure in the Workstation of	
	Wire Insertion Process	74
Figure	5.5 Workstation Standard Guide of Wire Insertion Process	75
Figure	5.6 Plan-Do-Check-Act Cycle for ACA 1	76
Figure	5.7 Proposed Standard Procedure of Wire Insertion	78
Figure	5.8 Additional Checkpoint in Common Process	
	OSG (Operation Standard Guide)	79
Figure	5.9 Comparison of Existing Wire Insertion Procedure	
	and Proposed Wire Insertion Procedure	80
Figure	5.10 Plan-Do-Check-Act Cycle for ACA 2	81
Figure	5.11 Proposed Preventive Maintenance Program	83
Figure	5.12 Crimping Machine Daily Evaluation Procedure	84
Figure	5.13 Crimping Machine Troubleshooting	85
Figure	5.14 Crimping Machine Monthly Preventive	
	Maintenance Procedure	86
Figure	5.15 Applicator Crimper Monitoring	87
Figure	5.16 Applicator Confirmation after 100,000 shots	88
Figure	5.17 Crimping Machine/Fixture Problem Report	89
Figure	5.18 Monthly Preventive Maintenance	
	Schedule for Applicator	90
Figure	5.19 Crimping Machine Daily Checklist	91

	Figure 5.20 Applicator Monitoring of 100,000 Shots Logsheet	95
	Figure 5.21 Crimping Machine Monthly Preventive	
	Maintenance Checklist	.96
	Figure 5.22 Operators Certificate of Understanding	97
	Figure 5.23 Plan-Do-Check-Act Cycle for ACA 3	98
Pictu	ires	
	Picture 3.1 Actual Crimping Inspection	43
	Picture 3.2 Actual Conduction Inspection	44
	Picture 3.3 Actual FQA Inspection	45
	Picture 3.4 Finished Goods: Wiring Harness (Company Product)	.46
	Picture 3.5 Parts of Wiring Harness	47
	Picture 3.6 Evidence Sample of Deformed Terminal	.48
	Picture 3.7 Criteria for Good Crimping Condition of Terminal	49
	Picture 3.8 Other Effects of No Proper Monitoring	
	of Crimping Machines	50
	Picture 3.9 Crimping Machine and its Components	.53
	Picture 3.10 Crimping Machine Sample Corrective Maintenance	55
	Picture 3.11 Evidence of Corrective Maintenance	.56
	Picture 3.12 Evidence Sample of Wrong Location of Wire	57
	Picture 3.13 Actual Wire Insertion Process in the Production	58
	Picture 3.14 Sample of Common Process	
	OSG (Operation Standard Guide)	.59

Picture 3.15 Evidence Sample of Half-Inserted	61
Picture 3.16 Other Effects due to No Standard	
Procedure of Wire Insertion	62

