

TOMS Manufacturing Corporation is Experiencing 5.19% Low Productivity in Machine  
21 Tray Exit Inner during February and April 2011 Amounting to Php 1,083,681

A Company Study Presented to the Faculty of the  
College of Engineering, Architecture, and Technology  
De La Salle University – Dasmariñas

Dasmariñas, Cavite

In Partial Fulfillment  
Of the requirement for Practicum 2

Submitted by:

Mark Anthony A. Hilario

IEE51

Submitted to:

Engr. Ma. Socorro Bunda

March 2011

## Abstract

This study focuses on eliminating the 5.19 Low Productivity in Machine 21 Tray Exit Inner, After some interviews and observations the researcher found out that TOMS Manufacturing Corporation was having a low productivity in machine 21 Tray Exit Inner. The reasons are lack of preventive maintenance, poor ventilation and unmotivated worker. After identifying these problems the researcher recommended, that first to implement a preventive maintenance to lessen the machine down time and production stoppage should be avoided. Second is to implement Monthly incentives to motivate the workers in their work and avoid absence and lastly purchase TORQ Industrial Blower which can resolve the problem of the worker regarding the ventilation in the working area. With these recommendations, the problem that was experience by the TOMS Manufacturing Corporations will be resolved.



## TABLE OF CONTENTS

Title page	i
Approval Sheet	ii
Acknowledgement	iii
Abstract	iv
Table of Contents	v
 <b>Tables and Figures</b>	
Table 1.1: Summary of the total output of mc21 From February 2011 to April 2011	15
Table 2.1: February machine down time	16
Table 2.2: March machine down time	16
Table 2.3: April machine down time	17
Table 2.4: Summary of downtime of mc 21	17
Table 2.5: Existing Preventive Maintenance	18
Table 3.1: Output of during the absence of Operator On mc 21	18
Table 4.1: Temperature in working area	19
Table 4.2: Output at 8:00 am- 12:00 pm	20
Table 4.3: Output at 1:00 pm- 03:00 pm	20
Figure 5.1: Schedule of Preventive Maintenance	31
Figure 5.2: Preventive Maintenance Check Sheet	32

**CHAPTER I: Introduction**

1.1. Background of the Study	2
1.2. Problem Statement	3
1.3. Objective of the Study	3
1.4. Scope and Limitation	4
1.5. Significance of the Study	4
1.6. Design and Methodology	6
1.7. Definitions of Terms	8

**CHAPTER II: Review of Related Literature**

**CHAPTER III: Presentation of Gathered Data**

**CHAPTER IV: Findings and Analysis**

4.1. Problem Tree	23
4.2. Objective Tree	25

**CHAPTER V: Alternative Courses of Action**

ACA 1: Improve Preventive Maintenance	27
ACA 2: Purchase TORQ Industrial Blower	34
ACA 3: Implement Monthly Incentive	35

**CHAPTER VI: Conclusion and Recommendation**

Gantt chart	38
Bibliography	41

**CHAPTER VII: ATTACHMENTS**