

**A STUDY ON MINIMIZING THE 3.78 PERCENT LOSS  
IN MANUFACTURING METFORMIN TABLETS  
AT SYDENHAM LABORATORIES, INC.**

**A Practicum Study Presented to the Faculty of  
College of Engineering and Technology  
De La Salle University – Dasmariñas  
Dasmariñas, Cavite**

**In Partial Fulfillment of the Requirements  
For the Degree of Bachelor of Science  
In Industrial Technology**

**Submitted By:  
PEROCHO, Ann V.  
FERRER, Katherine M.  
RAMIREZ, Rochelle L.**

**Submitted To:  
Engr. Orlando Lejos**

**Date Submitted:  
October 29, 2005**

**JUN 11 2008**

**AKLATANG ENHENS PASCUALDO ARCHIVES**

## TABLE OF CONTENTS

	PAGE
Approval Sheet	i
Acknowledgement	ii
<b>CHAPTER 1</b>	
1.1 Background of the Study	3
1.2 Company Profile	5
1.3 Statement of the Problem	7
1.4 Objectives of the Study	8
1.5 Significance of the Study	8
1.6 Scope and Limitations	9
1.7 Methodology Used for the Study	10
1.8 Definition of Terms	11
<b>CHAPTER 2</b>	
2.1 Presentation of Related Literature	12
Process Control	12
Process Principle of Wet Granulation	13
Process Principle of Blending	14
Process Principle of Drying	15
Metformin Tablet	16
<b>CHAPTER 3</b>	
3.1 Presentation of Gathered Data	17

	Production Report of Metformin Tablet	17
	Production Loss of Metformin Tablet	20
	Production Process Flow Chart	21
<b>CHAPTER 4</b>		
4.1	Analysis of Data	22
4.1.1	Problem Tree	23
4.1.2	Objective Tree	26
<b>CHAPTER 5</b>		
5.1	Presentation of Alternative Courses of Action	28
5.2	Cost and Benefit Analysis	36
<b>CHAPTER 6</b>		
6.1	Conclusion	40
6.2	Recommendation	40
6.3	Detailed Plan of Action	41
6.4	Gantt Chart	43
<b>Bibliography</b>		

## CHAPTER 6

### PRESENTATION OF CONCLUSION AND RECOMMENDATION

#### 6.1 CONCLUSION

In the course of the study, the main causes of the problems in percentage loss were the performance of the workers, improper use of tools and equipment and ineffective monitoring. The workers had been careless in performing their tasks especially in their manner of collecting and transferring bulks. The problems in monitoring occurred because of wrong computation of the output and the unavailability of the supervisor. Lastly, the problems existed because of the improper use of tools such as not using the required screen mesh size and poor maintenance of the filter bag.

#### 6.2 RECOMMENDATION

Based on the evaluation of the alternative courses of action, it is best to choose the first alternative, provide training and seminar of the workers. The said alternative will benefit both the workers and the company. The workers will benefit in such a way that they will gain enough knowledge and ideas regarding the operations. Thus, ensuring high level of work performance.