



Conclusions:

Based on the findings of this study, the following conclusions were formulated

1. There is designated entrance for visitor as part of the security measure of De La Salle University Dasmariñas for proper checking and identification.

2. Fire extinguishers are installed in places where they can be seen or noticed easily as part of the safety and security of De La Salle University Dasmariñas community. This are places that need additional lighting as part of security.

3. As part of the policies and procedure, sticker is issued as to allow vehicle to enter and there are designated parking areas for administrators, faculty, and students.



Recommendations:

Based on the findings and conclusions of the study, the following are recommended:

1. The officer in charge of checking and identification should be equipped completely to secure the safety proposes.
2. Fire extinguishers should be monitored regularly and they should be added more in place where they are needed. And addition lights and emergency lights for additional security.
3. The sticker should have designated color in every college as part of identification vehicle for propose of avoiding the replicate stickers.
4. Guards should be trained in attending seminar regarding security and safety education programs.
5. Administration should focus their budget on the improvement of security and safety equipment.